

**TEST REPORT****IEC 60364-4-41:2005****Low-voltage electrical installations – Part 4-41: Protection for safety –  
Protection against electric shock****IEC 61558-2-12:2001****Safety of power transformers, power supply units and similar —  
Part 2-12: Particular requirements for constant voltage transformers****Report**

Report reference No. .... : SCC(10)-083-2-10-LVD  
Tested by(+ signature)..... : *Liu Tong*  
Reviewed by(+ signature)..... : *Waylen*  
Approved by(+ signature)..... : *Hetis*  
Date of issue ..... : July 13<sup>th</sup> 2010  
Number of pages (Report) ..... : 33

**Testing laboratory**

Name ..... : CHINA CEPREI (SICHUAN) LABORATORY.  
Address ..... : No.45 Wenming Dong Road  
Longquanyi Chengdu 610100 P. R. China  
Testing location ..... : No.45 Wenming Dong Road  
Longquanyi Chengdu 610100 P. R. China

**Client**

Name ..... : Vanguard Power (Hong Kong) Limited  
Address ..... : 1501 Eastern Tower, Yihai Square Commercial Building, North  
Chuang Ye Road, Nanshan, Shenzhen, China

**Test specification**

Standard ..... : IEC 60364-4-41:2005+IEC 61558-2-12:2001  
Test procedure ..... : LVD  
Procedure deviation ..... : N.A.  
Non-standard test method ..... : N.A.

**Test report form/blank test report**

Test report form No..... : SCC60364  
TRF modified by..... : CHINA CEPREI (SICHUAN) LABORATORY..  
Master TRF..... : PS\_INFO\2-ELS.MES\REPORTS\CCA  
Copyright blank test report..... : This report is based on a blank test report prepared by CEPREI  
using information obtained from the TRF originator.